

Permission to print:	Yes
Category	Gas Supply
Near Miss or Accident	Near Miss
Type of incident:	Management
Knowledge Error	No
Rule Error	Yes
Skill Error	Yes
Violation	No

**Description:** It had been noted that Arterial Filters did not appear to be de-airing as well as usual by a number of perfusionists despite using normal CO2 flushing techniques. [It was subsequently] discovered that 2 out of 4 workstations [in the pump room] had CO2 lines to the HLM blender were plugged into [medical] air ports therefore flushing with air.

**Contributing factors:** CO2 gas lines [with a universal schraeder fitting between the HLM blender and the ceiling mounted CO2 supply line] fit into ports of the air lines [from the ceiling of the pump room]. HLM CO2 flush Lines are sometimes moved between workstations when lines are broken / being repaired.

**Corrective action:** Lines placed in correct CO2 supply ports.  
**Preventative action plan:** Replace the CO2 gas supply line from the ceiling with an uninterrupted line terminating in the unique CO2 connector to the electronic blender.

Manufacturer advised:	No
Discussed with team:	Yes
Ext Authority Advised	No
Hospital incident filed:	No
Patient outcome variance	Nil