

Permission to print:	Yes
Category	Heater Cooler unit
Near Miss or Accident	Near Miss
Type of incident:	Equipment
Knowledge Error	No
Rule Error	No
Skill Error	No
Violation	No
Description:	Stockert S3 Heater Chiller failed during bypass. Error code E28.
Contributing factors:	Electrical / Mechanical failure
Corrective action:	The heater Cooler unit was exchanged for different unit. The faulty unit was referred to clinical engineering for investigation
Preventative action plan:	Routine maintenance
Manufacturer advised:	No
Discussed with team:	Yes
Ext Authority Advised	No
Hospital incident filed:	No
Patient outcome variance	Nil